# Approved For Release 2004/08/3707FTRDP81B00961R000100180022-3

OSA-4144-64

9 SFP 1964

MEMORANDUM FOR THE RECORD

SUBJECT: Trip Report, EcCoy AFB, Orlando, Florida, 31 August - 2 September 1964

The Base Commander, Colonel James R. Wiley, conducted the tour of the base. The following observations were made:

# a. Hangar:

Building 407 identified as the North Mangar was selected for the operation. The building has sufficient space to house project aircraft. Details concerning power, minor construction, etc. will be furnished by

b. FEEL:

The Precision Reasurement Equipment Lab presents itself as a neat, fully equipped activity capable of performing calibration and repair on practically all types of test gear. Support can be furnished without difficulty if required.

# e. POL:

The POL facility is suitably located for convenient rail off-load and is in close proximity to the Horth Hangar. A small POL lab is situated near the fuel facility. The lab is available on a joint usage basis. There is sufficient dead trackage on the base for fuel storage. The usused trackage can accommodate twenty or more rail tank care. Switching service from the storage area to the off-load site is available on a daily basis. The off-load site has a rail spur running parallel to the main POL hydrants. The spur will hold six tank cars. Off-loading PF-lA fuel into R-2 units from the spur will not interfere with the base POL function.

Daygen - available

USAF review(s) completed.

Nitrogen - available

			22
EDSUITE TO	776		VI
		1	<del>}~;</del>
11 :.			
			2011
1. * 10 *		1.	

Approved For Release 2004/08/31 : CIA-RDP81B00961R000100180022-3

25X1

25X1

# Approved For Release 2004/08/31 \$100961R000100180022-3

ONA-4144-84

#### d. Vehicles:

Transportation on base is limited. Vehicle rentals can be obtained through consercial or GSA rental agencies. GSA and consercial rental agency representatives are located on base.

### o. Billeting:

Available quarters are adequate; however, the base can only provide quarters for one-half of the personnel involved. The remainder would have to seek quarters in motels or hotels off base.

# f. Messing:

The dining halls are adequate for all personnel.

#### . Other:

Office space is not available. Kention was made to the possibility of using trailers, or setting up within the hangar proper. Office furniture and equipment are not available. The base will purchase necessary items. We would have to provide the funds.

					25X1
PD/OSA-DD/S&T: Distribution:			(9 Sept 84)		
			D/FA/06A		
	**		SS/OSA		
	The state of		SD/OSA		
	4	-1950	MD/OSA		
	1	A <sub>P</sub> RF	B&F/OSA		
	3.	N/Sr	COMEO/OSA		
	19	*imi	RB/OSA		

25X1